











DUTCH WINDMILL
































23

23


1 - 22




Make sure the Gears mesh.

1 - 24


4x




4x



25 - 26



12 DUTCH WINDMILL



13 DUTCH WINDMILL