

















Rowboat



Did you install 2 AA (or LR6) batteries in the motor?

















9

3 - 8






15



14

14 - 15





16











14 - 15




14 - 16
















Rowboat

1 - 27



27



1 - 26