















Rowboat












Did you install 2 AA (or LR6) batteries in the motor?















15



14 - 15

14











16





14 - 15








14 - 16












Rowboat

1 - 27



27



1 - 26

